



N610074585AA Panasonic Fabricate 8 Head Suction Nozzle Exchange

Our Product Introduction

for more products please visit us on smtmachinepart.com

Basic Information

- Place of Origin: Japan
- Brand Name: Panasonic
- Model Number: N610074585AA
- Minimum Order Quantity: 1 PCS
- Price: USD+negotiable+pcs
- Packaging Details: 30*20*8cm
- Delivery Time: 1-7 days
- Payment Terms: T/T
- Supply Ability: 1+pcs+per days



Product Specification

- Brand Name: Panasonic
- Model Number: N610074585AA
- Product Name: 8-Head Suction Nozzle Exchange
- Condition: Original New/Used Original/Compatible New
- Lead Time: 1-7 Days
- MOQ: 1 PCS
- Highlight: **N610074585AA, Panasonic Suction Nozzle Exchange, 8 Head Suction Nozzle Exchange**



More Images



Product Description

1 Nozzle Holder

N610009409AA,N610009409AB,N610113250AB,N610071723AA,
N610126480AA,KXFB00S4A03,N610067607AE,N610097899AB,
N610063736AB,N210007398AA,KXFB03ZAA01,N210030755AA,KXFB029DB00,N210017657AA,KXFB00L1A02,
N210076717AA,KXF05ASAA00,KXFB0APUB00,KXFB0APUB00,
KXFB00S6A03,KXFB00S6A03,N210062110AA,KXF0DKAAA00,
N210007425AA,N210007425AA,KXF0DK9AA00,KXF0CPKAA00,
N610009394AC,N610009394AB,KXFX03EMA00,N610009394AB,KXFB02M2A01,KXFB02M2A00,N210007281AD,
N610011241AA,N610011241AB,N610113210AB,N610113210AA,KXFK001PA00,
N210014666AC,N210141026AA,N210125001AA,N210125002AA,
N210098763AB,N210007284AB,N610113699AA,N210081891AB,N210068065AA,N210068065AA,N210007287AB,
KXF0E07FA00,N510068212AA,N510068213AA,N510045029AA,KXFB02PPA00,

2 Ball Spline

N510054810AA,N510002505AA,KXF0DUPAA02,N510005433AA,
N510069637AA,N510054811AA,N510028739AA,N510024102AA,
N510028548AA,N510064708AA,N510040355AA,KXF0CWRRA01,
N210007491AA,N510037999AA,N510015534AA,N510005273AA,
KXF0DYEYA00,KXF0E41TA00,010DC081280,KXF0DTQAA01,
N510015781AA,N510011812AA,N510068462AA,N510064218AA,
N510051262AA,N510064219AA,N510068432AA,N510064335AA,N510056485AA,N510058687AA,N510067892AA,
KXFB0468A00,KXF0DXH7A00,

3 Nozzle

1001,1001tips,1002N,1004N,115A,110F,110,110N,115AN,120N,
130N,140N,161,161N,167A,161S,110S,110FS,115AS,120S,
130S,140S,110SN,115ASN,120SN,130SN,140SN,225C,226C,
226C WHITE HOLDER,226CN,230C,230CN,235C,235CN,240C,
240C WHITE HOLDER,240CN,205S,204S,204SN,206AS,225CS,
225CS WHITE HOLDER,225CSN,226CS,226CS WHITE HOLDER,226CSN,
230CSN,230CS,230CS WHITE HOLDER,235CS,235CS WHITE HOLDER,
235CSN,240CS WHITE HOLDER,240CS,240CSN,256CS,256CSN,203ZS,
203,205,205A,206A,208,450,452#,460#,178,185,185N,
199N,199,4247,2437,1421N,1404N,1416N,1377,2489,2488,4520

4 Grease

N510006423AA,N510017070AA,KXF05PLAA00,N990PANA-028,
N990PANA-027,N510048188AA,N610126470AA,KXFX038AA00,
KXF08V7AA00,KXF08V8AA00,1046601000,N510059330AA,
N510048190AA,KXF0DKRAA00,N510042737AA

5 Motor

N510042737AA,N510042738AA,KXF0DHSAA00,KXF0E1LXA00,
N510008188AA,N510042740AA,N510042739AA,MTNM000016AA,
N510048142AA,N510043555AA,N510043589AA,N510046420AA,
N510056943AA,N510027476AA,N510049987AA,N510022125AA,
N510022126AA,KXF0DX1BA00,KXF0DXE7A00,KXF0BLAA00,
N510048981AA,KXF0CWLAA00,N510005279AA,KXF0DXR9A00,
KXF0DXEMA00,KXF0DXEYA00,N510005280AA,N510057033AA,
KXF07R6AA00,N610063660AB,N510028282AA,N510034430AA,
KXF0DZDRA00,N510011993AA,N510011994AA,N510011995AA,
N510011996AA,N510029994AA,N510043454AA,N510042809AD,
N510042809AB,N510042809AD,N510055635AA,N510043455AA,
N510043456AA,308711300101,N510029993AA.

6 Head Unit

N610070248AA,N610073644AA,N210075411AA,N610056634AA,
N610007613AA,KXFY002LA00,N610007614AA,N610065885AA,
N610065886AA,N610065887AA,KXFX03KNA00,N610160410AA,
N610087794AA,N610162316AA,N610087764AA,N610162314AA,
N610119859AA,N610162467AA,

7 Monitor

N510062988AB,N510030800AC,N510011554AA,N610015977AA,
N610015978AA,N610015978AA,N510021011AA,

8 Feeder cart

KXFX036PA00,N610064416AA,KXF0DWLEB00,N210022016AA,
N610081683AA,N610049789AA,NM-EJW8A,KXF-407C,NM-EJK1A,
N610118830AA,N610146545AA,N510004571AA,N510004570AA,
N610083833AA,N210147640AA,N210181431AA,KXF0CVZAA00

9 Valve

KXF0DLLAA01,KXF0DLKAA01,N510063838AA,N510029538AA,
KXF0DR6AA00,N510063836AA,N510068101AA,KXF0A1RAA00,
N510054843AA,KXF0DX8NA00,KXF0DXETA00,N510054844AA,
N510028619AA,KXFX03WMA00,N510066930AA,KXF09X3AA00,
N510059431AA,KXF09X2AA00,KXF0DR3AA00,KXF0A3RAA00,
N510063835AA,MTNP000181AA,KXF0DR4AA00,N510033205AA,
010KC081210,KXF0A5GAA00,N510057239AA,N510034974AA,
N510051757AA,KXF0DXK2A00,N510031729AA,N510054465AA,
N41110VQ-714,KXF0A4NAA00,KXF0C8AAA00,
KXF0DXCNA00,N510055190AA,N510059940AA,KXF0DWM2A00,
N510010273AA,KXF0A6QAA00,N510058605AA,N510056948AA,
N610074285AC,

10 Sensor

N610026749AA ,KXF0DWVWA00 ,KXF0DWVWA01 ,N610040037AA ,
N610027221AA ,KXF0DWVXA00 ,KXF0DWVXA02 ,N610017022AD ,
N610017022AC ,N610017023AD ,N610017023AC ,N510025620AA ,
KXF0DQXAA00 ,KXF0DWP5A00 ,KXF0DU8AA00 ,KXF0DU8AA00 ,
KXF0DU9AA00 ,KXF0DU9AA00 ,N610016841AA ,N610024026AB , KXF0DXAJA00 ,KXF0DKYAA00 ,KXF0DKZAA00
,N510037012AA ,
N510037013AA ,N610002221AA ,N610002222AA ,N610006577AA ,
N610002260AA , N610002223AA , KXFY1541A00 ,KXF0DL8AA01 ,
KXF0E1KUA00 ,KXF0DL2AA01 ,KXF0DL7AA01 ,KXF0DTJAA01 ,
MTNS000433AA ,N510068524AA , N510054833AA ,MTNS000434AA , N510068525AA ,N510054834AA ,MTNS000435AA
,N510068526AA ,
N510054835AA ,MTNS000436AA ,N510068527AA ,N510054836AA ,
MTNS000432AA ,N510068515AA ,N510048693AA ,MTNS000430AA ,
N510068516AA ,MTNS000431AA ,N510068517AA ,N510037015AB ,
N510037016AB ,KXF0DSSAA00 , ,KXF0DSTAA00 ,KXF0D8LAA01 ,
N610009396AA ,N610009395AA ,N610088669AA ,

11 Belt

KXF0DKCAA00 ,KXF0DKDAA00 ,KXF0DKEAA00 ,KXF0DKFAA00 ,
KXF0DKGAA00 , N510010716AA ,KXF0E14SA00 ,N510027770AA ,
KXF0DXDTA00 ,KXF0DWXZB01 ,KXF0DWTDB00 ,KXF0E142A00 ,
KXF0E0R1A00 ,KXF0E0R1A00 ,N510027432AA ,KXF0DXQSA00 ,
KXF0DXDUA00 ,KXF0E0T9A01 ,N510004586AA ,N510004586AA ,
KXF0E1K3A00 ,KXF0E3ZJA00 ,N510010718AA ,KXF0E14ZA00 ,N510019317AA ,
N510002571AA ,N510019318AA ,N510022408AA ,N510058460AA ,
KXF0CT4AA00 , ,N510030308AA ,N510021326AA ,N510021327AA ,
N510055507AA ,N510028616AA ,N510034190AA ,N6417M615 ,
KXF08ANAA00 ,KXF0E08EA00 ,KXF0E08FA00 ,N510041655AA ,
N510060401AA ,N510061363AA ,N510059524AA ,N510061362AA ,
N510024044AA ,N510056484AA ,180GC184311

12 Service Driver

KXFP6GE1A00 ,KXFP6GB0A00 , ,N510002593AA ,N510002594AA ,
KXFP6F97A00 ,KXFP5WBAA00 ,KXFP5QBAA00 ,n510024098AA ,
N510044504AA ,MCDDT3520N45 ,MEDDT7364N45 ,N510058839AA ,
N510058840AA , ,N606MRJ2-234 ,

13 Feeder

N610117446AF , N610117446AC , KXFW1KS5A00 , KXFW1KSBA00 , N610031080AA ,KXFW1KS6A00 , KXFW1KSCA00
,N610133537AA , N610133538AA , KXFW1KS7A00 ,KXFW1KSDA00 , N610133539AA ,
KXFW1L0YA00 , N610133540AA , KXFW1L0TA00 ,KXFW1KS8A00 ,
KXFW1KSEA00 ,KXFW1KS9A00 , KXFW1L0ZA00 , KXFW1L10A00 ,
KXFW1L11A00 , N610005073AA ,KXFW1KSRA00 , N610056362AA , ,

14

Pc Board

KXFE0014A00 ,KXFE0004A00 ,KXFE00F0A00 , ,KXFE0001A00 , ,
N610090171AA ,KXFE00GXA00 , ,KXFE0005A00 ,N610013410AC ,
N610012654AA ,N610108741AA ,N610012673AA ,KXFE000HA00 ,
N610012674AB ,N610030275AA ,N610009178AA , KXFY001MA00 ,KXFK002EA00 ,N610008689AA ,N610067531AB ,
N610067530AB ,N610161300AA ,N510067651AA ,N610080208AA ,
KXFE000SA00 ,N610084745AA ,MTKB000020AA ,N610012675AB , ,
N610017211AA ,N510012086AA ,KXFK00APA00 , ,N610011654AA ,
N610001129AA ,KXFE00FGA00 ,N610020291AA ,KXFK001PA00 , ,
N610032084AA ,KXF0DWITHA00 ,KXFE001VA00 ,MAC9006B01 ,
KXFE000JA00 ,MTKB000022AA ,N610110532AA ,KXFP5Z1AA00 ,
KXFE000MA00 ,MTKB000021AA ,N610061446AB ,KXFX036HA00 ,
N510023795AA ,N510028496AA ,KXF0DWVRA00 ,N510023803AA ,
N510023802AA ,N610168458AA ,N610136337AA ,KXFE000EA00 ,
KXFE0009A00 ,KXFE0008A00 ,N610140450AA ,N610051792AA ,
N610010912AA ,KXFE00GQA00 ,N610050355AA ,KXFE000LA00 ,
N610087118AB ,N610012076AA ,KXFE0002A00 ,N610110715AA ,
KXFE00FKA00 ,N610001943AA ,N610001944AA ,KXF0DUWAA00 ,
N610136306AA ,N610102505AA ,N610118835AA ,N510041187AA ,
N610168882AA ,KXFE001AA00 ,KXFK001MA00 ,KXFE00DUA00 ,

15

Power

KXFP654AA00 ,KXFP6GE3A00 ,KXFP5T3AA00 ,KXFP6EM4A00 ,
N510053339AA ,KXFP6CJAA00 ,KXFP6GFZA00 ,KXFK002XA00 ,N510009961AA

16

Cables

N510053281AA ,KXFP6E1AA00 , ,N510028646AB ,N510028646AB ,
N210060009AC ,N610073915AC ,N610073915AC ,N610119365AD ,
N610129395AA ,N610111706AA ,N610111705AA ,KXF0DYEA00 ,
KXF0CWPAA00 ,KXF0CWMAA00 ,N510002655AA ,N510009023AA ,
KXF0E1H2A00 ,N510059933AA ,N510028368AA ,N510019114AA ,
N510026295AA ,N510026292AA ,N510026293AA ,N510026294AA ,
N510026267AA ,N510026215AA ,N510026217AA ,N510012770AA ,
N510012758AA ,N510013509AA ,N510013510AA ,N610060831AA ,
KXFYGC00224 ,N610152894AA ,N610152898AA ,N510013986AA .

17

Jig

N610036851AA ,KXF0DXKJA00 ,KXFX037HA00 ,N610003318AA ,

N610003319AA ,KXFX037KA00 ,KXFY00A3A00 ,KXFY00A4A00 ,
KXFX037GA00 ,N610124226AA ,N610030591AA ,N210141055AA ,
KXFX037JA00 ,N610008706AA ,N610008707AA ,N610030932AA ,
N610030935AA ,N210133398AA ,N210130779AA ,N21015167AA ,
N610087275AA ,KXFYGC00424 ,ERJJ02AAAAAV ,KXFYGC00425 ,
MTKA008066AA ,N210005938AA ,N210005939AA ,N210005940AA ,
N210005941AA ,N210005942AA ,N610005808AB ,N610015631AB ,
N610021925AA ,N610012677AB ,N510011301AB ,N510044812AA ,
N510044810AA ,N510044809AA ,KXFB03KAA01 ,1089696451 ,
N610067369AB ,N510061701AA ,N610130890AB ,N510067200AA ,
KXF0DXJ6A00 ,N210112529AA ,KXF0DXJ4A00 ,N610076207AA ,N610108752AA ,
KXF095GAA00 ,N610032106AA

18 LINEAR WAY

KXF0DWYXA00 ,KXF0DXJ5A00 ,010CC083020 ,KXF0DY1QA00 ,
KXFYGC00483 ,N510006050AA ,N510054618AA ,N510015478AA , ,
KXFYGC00482 ,N510023677AA ,MTNB000021AA ,MTNB000022AA ,
N510030818AA ,

19 Ball Screw

KXF0DXGWA00 ,010CC082111 ,010CC083011 ,010CC082101 ,
KXF0DXGWA00 ,N510029898AA ,KXFY006WA00 ,KXFK001LA01 ,
N510015477AA ,N510015479AA ,N510034429AA ,N510031728AA

20

Pulley

N610116865AA ,KXF0E0GGA00 ,N510010794AA ,KXF0DWP0A00 ,
N610116866AA ,N510002167AA ,KXF01LFAA00 ,110HC181201 ,KXFB02QLB00

21 Other

N510037839AA ,N610014970AE ,KXF0E3RRA00 ,KXF0E3RRA00 ,
N4520403-142 ,N610071334AA ,N210048234AA ,N510059196AA ,
N510059928AA ,N510059866AA ,N510054846AA ,N210097217AA ,
N510062040AA ,KXF0DT5AA00 ,N510062045AA ,N510035445AB ,
N510062039AB ,N610124205AC ,KXF0ARVAA00 ,000JC081100 ,
108111001801 ,KXF0DXTAS00 ,KXF0DXESA00 ,N610034897AA ,
KXFX03E3A00 ,KXF0A6PAA00 ,KXF0DXFYA00 ,010DC081044 ,
N610025628AA ,KXF0DXTSA00 ,150NC381211 ,KXF016EAA00 ,
N510069565AA ,N610133066AA ,N610087389AA ,KXFX036UA00 ,
KXFX036JA00 ,N610108392AA ,KXFB00VCA01 ,N210113757AC ,
KXF0DHMAA00 ,N210049814AF ,KXF0CSQAA00 ,KXF05YHAA00 ,
N555MYA3 ,KXF0DS4AA00 ,KXF0DXF3A00 ,N610144922AB ,
KXF0DXU4A00 ,KXFYGC00467 ,N610144923AA ,KXF0A3EAA00 ,
KXF0A3EAA00 ,N510013496AA ,KXF0DZVXA00 ,N510013497AA ,
KXF0DWRPA00 ,KXF0E1VCA00 ,KXF0E381A00 ,KXFX03EJA00 ,
N610027892AA ,KXF0B1DAA00 ,KXFB02E1A00 ,N510034869AA ,
KXF0DMAAA00 ,N210175463AA ,KXF0E0LYA00 ,N510047260AA ,
N510068689AA ,N510027039AA ,N510027040AA ,N510027041AA ,
N510027042AA ,N510027043AA ,KXF0DHZAA00 ,KXF0DZBAA00 ,
KXF0DXM1A00 ,KXF0DXM1A00 ,KXF0DWWEA00 ,N510019323AA ,
KXF0DLFAA00 ,KXF0D32AA00 ,KXF0CWGAA00 ,N902YD70-242 ,
KXF07QVAA00 ,KXF07QVAA00 ,N210158626AA ,KXF07QUAA00 ,
KXF07QUAA00 ,N210158627AA ,N510041345AA ,N210052484AA ,
N510016346AA ,KXF0DJSAA00 ,N510011382AA ,KXF02G7AA00 ,
N610008158AA ,N510003585AA ,KXF00RNAA00 ,KXF00RWAA00 ,
KXF00RMAA00 ,N510011403AA ,KXF0CSVAA00 ,N510011405AA ,N510033224AA ,KXF0DZXDA00 ,N510017123AA ,
N510003588AA ,

N510019154AA ,N510003597AA ,N510003602AA ,N510017124AA ,
KXF0A1SAA00 ,KXFB03KPA00 ,N510055859AA ,N510015026AA ,
KXF0DWTLA00 ,N610029094AB ,N610128950AA ,N610002225AB ,
KXF0DVEAA00 ,N610123946AA ,KXFB02MJA02 ,N210052182AA ,
N210029161AA ,KXFX037AA00 ,KXFX03ERA00 ,KXFX03FMA00 ,
N610026560AA ,N610070358AA ,N510068160AA ,KXF0DWLQB00 ,
KXFB029SA00 ,KXFB02LBA00 ,KXF038NAA00 ,KXF0KEWAA00 ,
N210020696AA ,N510059865AA ,N510067900AA ,KXFX037PA00 ,
N210088855AA ,KXFB02E0A01 ,N510018483AA ,N510026233AA ,
N210160059AA ,N510018469AA ,N510018266AA ,N510017097AA ,
N210007288AA ,N510047259AA ,

22

Spare part

for NPM

N510035086AB ,N610119286AC ,N610121359AA ,N610102197AA ,
N510051935AA ,N510059745AA ,N610133687AA ,N510053278AA ,
MTNS000234AA ,N510028418AA ,N610136398AA ,N510054904AA ,
N510054905AA ,N510054713AA ,N510054714AA ,N610102507AC ,
N610097972AA ,N610106340AA ,N610121793AA ,N610099138AA ,
N510040630AA ,N610059330AA ,N610063804AA ,N510037232AA ,
N510039754AB ,N510066469AA ,N510047869AA ,N510031655AA ,
N510038241AA ,N510040354AB ,N510040353AB ,N610034743AA ,
MTNP000831AA ,

Spare part

for HDF

N610103817AA ,104305971104 ,104837003101 ,10483S0011AA ,

10HKC0M0000 ,10HKL0M0000

Feeder

spare parts

N210047118AB,N210050452AA,N210050453AA,N210050454AA ,
N210050455AB , ,N210050456AB,N610092834AC,N610002833AA,
N210103441AB,N210005449AA ,KXFA1PT7A00 ,N210064344AC ,
N610025484AB ,N610025484AA ,N610025485AB ,N610025485AA ,
KXFA1KFAA00 ,N210045625AA ,KXF0DK4AB00 ,N210109639AA ,
KXFA1PT4A00,KXFA1L0AA00,N210109640AA ,KXFA1PT5A00 ,
N210114131AA ,N210157019AA ,N210099708AC ,N610030637AC ,
KXFA1L6AB00 ,N610027558AD ,N610014407AC ,N610014407AC ,
N610037299AB ,N610037916AB ,KXFA1LMAA00 ,KXFA1PQ7A02 ,
KXFA1PQ8A02 ,N210005305AA ,N610037300AB ,N210120308AA ,
N610090958AA ,N610002834AB ,KXFA1PQ9A00 ,KXFA1PR0A00 ,
KXFA1MQBA00 ,KXFA1MPBA01 ,KXF0DWTKA00 ,N610033140AA KXF0DWTLA00 ,N610033141AA ,KXFA1PR1A00
 ,KXFA1N8BA01 ,
KXFA1N6BA00 ,KXFW1L15A02 ,KXFW1L16A01 ,N610025479AB ,
KXFA1KLAA00 ,KXFA1KEAA00 ,KXFA1KRAA00 ,N210029789AA ,
N210038151AA ,N610090959AA ,N210029790AA ,N610025480AB ,
N610025478AD ,KXFA1MLAA00 ,KXFW1KXLA00 ,KXFA1PS9A00 ,
KXFA1PS9A00 ,KXF0DK1AA00 ,N510018477AA ,N610011374AA ,
N610090963AA ,N210159202AA ,N210159202AA ,KXFA1LHAA00 ,
N510002400AA ,KXFA1LTAA00 ,KXFA1KRAA00 ,KXFA1L0AA00 ,
N510002408AA ,N510025484AA ,N510025485AA ,N510018959AA ,
KXF08WXAA00 ,KXFA1PQ5B00 ,KXFA1Q0LA00 ,KXFA1NNAA00
N210081355AB ,N210038151AA ,KXF0DYAJA00 ,N610072585AC ,
N610081167AB ,KXF0DYUFA01 ,N210006455AA ,KXFW1KWJA00 ,
KXFA1KPAA00 ,N210116209AA ,N210045625AA ,KXFA1KQAA00 ,
N210146695AA ,N210017141AA ,N210071635AA ,KXFA1LQAA00 ,
KXFA1KHBA00 ,N210006455AA ,XSS3+6VW ,N210120309AA ,
N510018477AA ,N210089630AB ,KXFA1PR5B01 ,N210029789AA ,
KXFA1NBAA00 ,KXFA1LDAA00 ,N610072586AB ,N210006457AA ,
KXFA1P3AA00 ,KXFA1Q0PA00 ,KXFA1LPBA00 ,KXFA1PT9A01 ,
KXFA1PSYA02 ,KXFA1KAAA00 ,XSS25+6VW ,XSN25+3VW

Global Soul Limited

sales@gs-smt.com



N610074585AA Panasonic fabricate 8-Head Suction Nozzle Exchange | GSSMT, Panasonic nozzle changer types, Panasonic nozzle changer specifications, Panasonic nozzle changer installation, Panasonic nozzle changer price, Panasonic nozzle changer maintenance, Panasonic nozzle changer compatibility, Panasonic nozzle changer review, Panasonic nozzle changer features, Panasonic nozzle changer troubleshooting, Panasonic nozzle changer benefits, Panasonic nozzle changer operation, Panasonic nozzle changer parts, Panasonic nozzle changer automation, Panasonic nozzle changer performance, Panasonic nozzle changer for SMT, Panasonic nozzle changer upgrade, Panasonic nozzle changer guide, Panasonic nozzle changer accessories, Panasonic nozzle changer catalog, Panasonic nozzle changer supplier



Global Soul Limited



+8613728696610



liyi@gs-smt.com



smtmachinepart.com

Room F3B-016, B Block, Hao Yun Lai Bussiness Building, Liutang road , Bao'an District , Shenzhen, China